General Environmental Incident Summary

Responsible Party:	Soo Line Railroad	DEW MCIG	
Date Incident: 2/8/		Duration:	
County: Burleig	gh <i>Twp:</i> 138 <i>Rng:</i>	80 Sec: 3 Qtr: N	IE
Lat: 46.80198	Long: -100.76260 Method	: Derived from TRS	
Location Description	on: Between Bismarck and Dral	Се	
Submitted By:	bmitted By: Affiliation:		
Address:			
City:	S	tate: Zip:	
Received By:			
Contact Person:	Bill Sanborn		
	,		
Distance Nearest (Occupied Building:		
Type of Incident:			
Description of Rele	eased Contaminant: Diesel fu	əl	
Volume Spilled:	100.00 gallons	Ag Rel	ated: No
EPA Extremely Ha	zardous Substance:	Reported to	NRC: No
Cause of Incident:			
TANK ON LOCOMO	OTIVE LEAKED. SPILL BETWE	EN BISMARCK AND DRAF	Œ.
Risk Evaluation:			
# of Fatalities:	# of Injuries: A	ffected Medium:	
" or r atamerour	C. I.Julicei	Toolog modium	
Potential Environn	nental Impacts:		
Potential Environm	nental Impacts:		
Potential Environm Action Taken or Pi	·		
	·		
	lanned:		

Wednesday, May 07, 2014 Page 1 of 2